Oil Field Environmental Incident Summary

Responsible Party: Williston Hunter ND, LLC

Well Operator: WILLISTON HUNTER ND, LLC

Well Name: Mohall Madison Unit

Field Name: MOHALL Well File #: 0

Date Incident:8/24/2013Time Incident:10:02Facility ID Number:403714-01County:BOTTINEAUTwp:161Rng:83Sec:6Qtr:SW NE

Location Description:

Submitted By: John Eide Received By:

Contact Person: Scott Hunskor

410 17TH STREET, SUITE 1000

DENVER,, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spillea	Units	Recoverea	Units	
Oil	2	barrels	2	barrels	
Brine	54	barrels	54	barrels	
Other	0	barrels	0	barrels	

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Followup

Units

Potential Environmental Impacts:

Action Taken or Planned:

Shut wells in, contact tanker truck to pick up liquid contained in dike, scrape up stained dirt. Wash out treater, inspect, and decide if treater is able to be repaired.

Wastes Disposal Location: recoverable liquid will go into storage tanks, scraped up dirt will be hauled to approved waste facility

Agencies Involved:

Updates

Date: 8/28/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, within the treater dike, according to the report.